


Safe Working around Tele Handlers

Working around Tele Handlers is dangerous work; ensure you comply the guidance given below



- ✱ Zone 1 - Always signal the plant operator and receive a positive response before entering Zone 1
- ✱ Zone 2 - Keep out of at all times
- ✱ Anyone approaching plant must make eye contact with the operator and wait until signalled
- ✱ Plant and Vehicle Marshals must wear the correct colour PPE and identification as per the site rules
- ✱ Plant operators are to ensure that safety levers are activated, machines are switched off and buckets (or attachments) are grounded before people approach

